

BUILDING SAFETY CERTIFICATE

No. 791,

Dated: 13-02-2025

It is certified that the existing building BAS INTERNATIONAL ENGLISH MEDIUM SCHOOL NIDAGUNDI ROAD, MUDDERIBHAL (name of the building or premises) at HADALAGERI (address) is having block(s)/Floor(s) as per details below.....


Details of Block (s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No of Floor (s) in the Block	Ground Floor	First Floor				

The building is owned/occupied by BAS INTERNATIONAL ENGLISH MEDIUM SCHOOL NIDAGUNDI ROAD, MUDDERIBHAL (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PWD Sub-Division MUDDERIBHAL (Name of Department/ Govt.) on 10.02.2025 (date of inspection) in the presence of...ADAMMA.S.BIRADAR..Secretary (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from June-2025 to May -2027 for a period of 2 years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1) In the coming days, if any damages like collapse/cracks/water leakage etc. are found in any part of the building, immediately report to the competent authority and take immediate steps.
- 2) Obtain a Fire Safety certificate from the Fire Department and implement the recommendations given by them, and renew the said inspection report periodically.
- 3) Keep the original documents of the building properly.
- 4) During the building inspection, if any minor cracks, or dampness on the walls are found, after repairing the same, the building can be used.

Issued On at 13.02.2025 by Shri Ayyappa Reddy AE-2

* Strike out whichever is not applicable. In case of block is more than six separate sheet for details


(S, 10)

Signature with Seal:

Name : **Assistant Executive Engineer**
PWD Sub Division, Muddebihal.

Designation :

Name & Address of Department/Officer